

This document is a translation of the original document in Lithuanian. In case of discrepancies between this translation and the Lithuanian original text, the Lithuanian text shall prevail in the interpretation of the content.

On the submission of a safety investigation report and safety recommendations

From [...]

Date 2025-04-02, Tr 10:51

To [...]

■ Attachments: 2 (3 MB)

II.OM.OM3 2.4 Degalų ir alyvos kiekio nustatymas.pdf; II.OM.OM2 3 Avarinės Procedūros.pdf;

Good afternoon,

In reply to your letter No (8.4.4E) 3A-6 of 9 January 2023, "On the submission of a safety investigation report and safety recommendations".

Safety Recommendation No SR-2022-A-05

The ATO Handbook, Volume II, Part 3, Chapter 2.4, Fuel and Oil Determination, describes an additional procedure for managing fuel consumption.

Safety Recommendation No. SR-2022-A-08

ATO Manual Volume II, Part 2, Volume II, Part 2, Chapter 3, Emergency Procedures, describes abnormal and emergency procedures, and decision making and emergency management.

Pagarbiai / With best regards,

[...]

[...]

T: [...]

E: [...]

W: www.pilotumokykla.lt

A: Rodūnios kelias 34, Vilnius, LT-02187, Lithuania

PILOTŲ MOKYKLA 
PILOT TRAINING CENTER

